

Oil Field Environmental Incident Summary

Incident: 20141222163446 **Date/Time of Notice:** 12/22/2014 16:34

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P VANDEBERG 154-99-1-1-12-15H3

Field Name: STOCKYARD CREEK

Well File #: 26378

Date Incident: 12/7/2014 **Time Incident:** 01:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 99

Sec: 1

Qtr:

Location Description:

Submitted By: Sarah Paycer

Received By:

Contact Person: Sarah Paycer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.3 Mile

Distance Nearest Water Well: 0.3 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons	2	Gallons	10	gallons
Brine	10	Gallons	2	Gallons	10	gallons

Other

Description of Other Released Contaminant:

Mist sprayed South across location.

Inspected:

Written Report Received: 12/23/2014

Clean Up Concluded: 12/22/2014

Risk Evaluation:

TBD

Areal Extent:

100'x100'

Potential Environmental Impacts:

TBD

Action Taken or Planned:

Impacted materials on site have been cleaned up. Snow effected by the mist will be scooped up and taken to Indian Hills Landfill. A survey was completed on 12/18/2014 of the impacted off site area.

Wastes Disposal Location: Indian Hills Landfill

Agencies Involved:

Updates

Date: 12/23/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12/23/14.

Minimal impact to the field to the east of the flare. Impacted material has been scraped up and placed in a rolloff container owned by Indian Hill Disposal.

No followup is necessary.

Date: 12/23/2014 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, sprayed off location. Followup is necessary. According to report contact, late reporting date due to fact that incident originated with previous owner of wellpad. Landowner has been contacted by company.